

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig 1. 45 inch driver miss ellipse pattern




Fig 2. Lie Angle - α Definition




Figure 3. Setup Angle - β Definition




Figure 4. Driver Setup angle - β as a function of shaft butt height at address

Comparison of Standard Lie Angles to Setup Angles for Irons




Figure 5. Comparison of standard lie angle - α and setup angle - β for irons

Set-up of Jim Reynolds - circa 1932




Figure 6. Driver Setup Angle as shown by Jim Reynolds in 1932




Figure 7. Forces on the club head due to gravity




Figure 8. Enhanced Performance club head design




Figure 9. Impact Hit Patterns on a Standard Lie Driver




Figure 10. Impact Hit Patterns on an Improved Design Driver




Figure 12. Charts showing the Results of Tests Conducted with a Driver Designed in Accordance with the Present Invention




Figure 13. Top view of club head